

Stantec

**BROOKE-ALVINSTON WIND FARM
WATER REPORT**

Appendix B

Site Photos



Photo 1: Looking west from Ebenezer Road at shallow depression in pasture land within the study area (Site A north in field notes).



Photo 2: Looking east from Ebenezer Road at pasture land within the study area (Site A north in field notes).



Photo 3: Looking west from Ebenezer Road at shallow depression in pasture land within the study area (Site A south in field notes).



Photo 4: Looking east from Ebenezer Road at shallow depression in pasture land within the study area (Site A south in field notes).

